

VEHICLE INSPECTION REPORT

8076

NIFTY LIFT HR12 NDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date		Fuel Type	ELECTRIC	Body Style	Access Platform
Year		Colour		Gearbox	MANUAL
Mileage	Not Showing	VIN	8076	Axle Combi	2WD

WILL NOT START, NO CHARGERS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



